CF03 - Runaway Phenomenon

Error code	Cause	Result
CF03	Runaway phenomenon	The motor works at high speed as soon as the system is turned on.

Troubleshooting

Step 1 Replace the controller.

Replace a new controller to see if it's controller issue.

Specification	Solution
Problem solved.	Repair complete.
Error still happen.	Go to step 2

Step 2 Replace the sensor.

Replace a new sensor to see if it's sensor issue.

Specification	Solution
Problem solved.	Repair complete.
Error still happen.	Contact BAFANG.